



IECEX Quality Assessment Report Summary

INTERNATIONAL ELECTROTECHNICAL COMMISSION IEC Certification System for Explosive Atmospheres

for rules and details of the IECEX Scheme visit www.iecex.com

QAR Ref. No.:	DE/EPS/QAR14.0012/12	Page 1 of 1
QAR Free Ref. No.:	26TH0025_A1	Status: Issued
Details of change:	Renewal audit completed	Date of issue: 2026-04-27
Location(s) audited:	QLight Co., Ltd. 185-25, Mukbang-Ro Sangdong-Myeon Gimhae-Si Gyeongsangnam-Do Korea, Republic of	Valid until: 2029-04-27 Audit date: 2026-04-21
Issuing ExCB:	EPS - Bureau Veritas Consumer Products Services Germany GmbH	
Manufacturer:	QLight Co., Ltd. 185-25, Mukbang-Ro Sangdong-Myeon Gimhae-Si Gyeongsangnam-Do	
Location of Manufacturer:	Korea, Republic of	
Product information:	signal lamps, signal lamps and speaker, flame-proof warning light, limit switch SLP	
Type of protection:	increased safety "e", flameproof enclosures "db", protection by enclosure "tb" optical radiation "op is"	
Related QARs:		
DE/EPS/QAR14.0012/00	DE/EPS/QAR14.0012/01	DE/EPS/QAR14.0012/02
DE/EPS/QAR14.0012/03	DE/EPS/QAR14.0012/04	DE/EPS/QAR14.0012/05
DE/EPS/QAR14.0012/06	DE/EPS/QAR14.0012/07	DE/EPS/QAR14.0012/08
DE/EPS/QAR14.0012/09	DE/EPS/QAR14.0012/10	DE/EPS/QAR14.0012/11
Related Certificates (manual insertion)::		
Related Certificates (automatic linking)::		
Related Certificates for previous versions:		
IECEX EPS 14.0041X issue: 0	IECEX EPS 14.0041X issue: 1	IECEX EPS 14.0041X issue: 2
IECEX EPS 14.0060X issue: 0	IECEX EPS 14.0060X issue: 1	IECEX EPS 14.0060X issue: 2
IECEX EPS 14.0060X issue: 3	IECEX EPS 14.0060X issue: 4	IECEX EPS 14.0060X issue: 5
IECEX EPS 15.0030X issue: 0	IECEX EPS 15.0030X issue: 1	IECEX EPS 15.0030X issue: 2
IECEX EPS 18.0012X issue: 0	IECEX EPS 18.0012X issue: 1	IECEX EPS 18.0012X issue: 2
IECEX EPS 18.0012X issue: 3	IECEX EPS 18.0012X issue: 4	IECEX EPS 21.0030X issue: 0
IECEX EPS 21.0030X issue: 1	IECEX EPS 24.0023X issue: 0	IECEX ICR 26.0003X issue: 0
IECEX KSCP 21.0012X issue: 0	IECEX KSCP 21.0012X issue: 1	IECEX KSCP 21.0012X issue: 2
IECEX KTL 18.0029X issue: 0	IECEX KTL 18.0029X issue: 1	IECEX KTL 18.0029X issue: 2

Comments: